


CORNER RECORD

Document Number 98-165

City of RIVERSIDE

County of RIVERSIDE, California

Brief Legal Description LOTS 2-3-4, BLK. 38, M.B. 11/20-21 (S.B. CO.) IN NW 1/4 SEC. 16, T. 3S, R. 5E
(Include: Sec., Twp., Rge., and Meridian or Rancho)



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey FEB. 2, 1998

COORDINATES (Optional)

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
SEE PLAT ON PG. 2

A description of the physical condition of the monument as found and as set or reset:
SEE PLAT ON PG. 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on FEB. 4 1998.


Signed Joseph N. Beeler L.S. ~~4055~~ Number 4055



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 5 1998 and examined and filed August 5 1998.

Signed Michael C. Parks Title Senior Land Surveyor



County Surveyor's Comment _____

THE FILING OF THIS CORNER RECORD
DOES NOT RELIEVE THE SURVEYOR
FROM ANY RESPONSIBILITY OF THE
FILING OF A RECORD OF SURVEY